

Peñuelas Valley Landfill, LLC. PO Box 918 Punta Santiago, PR 00741-0918

June 15, 2018

Team Leader
Clean Water Act Team
Multimedia Permits and Compliance Branch
Caribbean Environmental Protection Division
US Environmental Protection Agency, Region 2
City View Plaza II, Suite 7000
Guaynabo, PR 00968-8069

Director, Water Quality Area Environmental Quality Board PO Box 11488 San Juan, PR 00910

Re: Administrative Compliance Order

Peñuelas Valley Landfill, LLC./EC Waste, LLC.

Docket Number CWA-02-2017-3103 NPDES Tracking Number PRR053203

**Progress Report** 

Dear Team Leader:

The referenced order requires submittal of a progress report of corrective actions to be completed to reduce the total suspended solids (TSS) in the discharge. Peñuelas Valley Landfill (PVL) has continued to take measures to lower the TSS in the discharge. This report covers the month May 2018. During the period there were sporadic rain events that did not generate a discharge that could be sampled. During the period the site registered 2.11 inches of precipitation. The sedimentation pond is designed to hold approximately five feet of water before there is a discharge. The current water level in the pond is more than 4 feet below the overflow level.

The site continues to provide maintenance to erosion and sedimentation control devices as necessary. Silt fences are being kept in place and new ones installed were needed. Additional energy dissipaters have been installed on the storm water down chute near the soil extraction area (see enclosed photo). In addition, the site also continues to perform road spraying for the control of fugitive dust and periodic road washing is being performed to prevent mud accumulation and potential discharge during heavy rain events.

PVL continues to evaluate methods for the control of TSS in the storm water discharge. As part of the efforts to identify solutions for the control of TSS PVL collected a grab sample from the water that is accumulated in the sedimentation pond. The sample was collected on May29, 2018. There were no significant rain events during the 10 days before the sampling event. The TSS result for the pond sample was 248 mg/l which is similar to the 240 mg/l result for the sample collected from the discharge on March 23, 2018. The site continues to evaluate the situation in order to resolve this matter and bring it to a conclusion.


The statement below follows the requirements of the request for information. The questions and requested presented in the request for information are answered in the attached document.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. 1 am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Should you require additional information please contact Jaime Jaén on 787-391-0074 or René Rodríguez on 787-447-2717.

Cordially,

René R. Rodriguez Director of EH&S Compliance





SABANETAS INDUSTRIAL PARK · BLD. M-1380 · PONCE, PR 00731
P.O. BOX 359 · MERCEDITA, PR · 00715-0359
TELS. (787) 835-4242 · (787) 848-6050 · FAX (787) 848-6299 · (787) 835-2004
www.altolenterprises.com · info@altolenterprises.com

## REPORT OF ANALYSIS

Certificate Number: CERT - 24541

June 7, 2018

Customer Name:	EC WASTE	Cu	Custody Number: 93599							
Contact:	MARIA VIDAL		Sampled Date: Tuesday, May 29, 2018							
Customer Address:	P O BOX 918	:	Sampled Time: 0940 hrs.							
	PUNTA SANTIAGO		Received Date: Wednesday, May 30, 2018							
Phone/Fax:	787-836-3700	Sample F	Received Time:	: 1505 hrs.						
Contact Email:	mvidal@ecwaste.com		Sample Matrix:	Liquid						
Sampled By:	María Vidal		Sample Type:	Grab						
Sample Received By:	S. Aponte	Temp Re	Temp Received at Lab: 2 °C							
Sample Delivered By:	D. Cales	Lab. Sa	Lab. Sample Number: AT-18-3238							
Project and Sample Description:	Water Test Charca de Sedin	nentación								
Parameter	Units	Result	Discharge Limit	Method	Method Detect Limit	tion	Analysis Date	Analysis Time	Analyst	
Total Suspended Solids	mg/L	248	250	SM 2540D	4.0		May 31, 2018	1015	JB	

Saira Vázquez Báez

Laboratory Operations Director

Licensed Chemist #54/71

A 1670993





ALTOL CHEMICAL ENVIRONMENTAL LABORATORY, INC. SABANETAS INDUSTRIAL PARK, EDIFICIO M-1380, PONCE PR 00731

PO Box 359 Mercedite, PR 00715

TEL.787-848-6050 FAX: 787-848-6299



Customer Company Name & Address:	Contrar of Contrar				_			COUH 1532	4	CUSTODY #	-	•
	Maria Maria	Customer Contact (Print name & sign):  *Maria Vidal				METALS		WET CHEMISTRY				CHROMATOGRAPHY
EC waste	.0.1	01/100				Aluminum (A,C)		Acidity (A)		Phenol (A)		BTEX (A.E.)
	(AMAI)	- Vial	nl			Antimony (A,C)		Alkalinity (A)		P. Total (A, B)		BTEX (A)
Project Name:	VVIVALLE	e pucc	16		-	Arsenic (A,C)	_	Ammonia (A,B)		Res. Chlorine (A)		Chloroform as TTO (A) (E)
Chemical test					$\vdash$	Barium (A,C)		Asbestos (A)		Set. Solids mg/L (A)		Dioxin (A)
Project Address: //		Tohanai			-	Berrilium (A,C)		Bicarbonate (A)	L	Set Solids ml/L (A)		MIBK(A)
l'envel95		Phone:			<b>—</b>	Bismuth (A,C)	_	BOD-5 (A)		Silica (A)		MTBE(A)
TURN AROUND TIME: Rush Days X Norm	Invoice to sample	10	1		-	Boron (A,C)	_	Bromide (A)		Solids Total (A)		PCB'S(A) 8082 608 (A)
TITOSTI TORYS IT NOTH	SAMPLE TYPE	Owner		onsultant	-	Cadmium (A,C)	_	CaO MgO (1)		Sulfate(A)		Pesticide - TTO (A)
Chemical Microbiology Source Wa		SAMPLE MATRIX  X Liquid		NTAINERS	+-	Calcium (A,C)		Carbonate (A)		Sulfide UND (D,H,A)		Phenois by GC (A)
ENVIRONMENTAL CONDITION Waste Wat	1	Solid		terile lastic	⊢	Chromium (A,C)		Chloride (A)	_	Suifite (A)		TBA (A)
Sunny Cloudy Ground Wa		Oil		lass	-	Chromium VI (A,C)	_	COD (AB)	-	Surfactant (A)		TPH_D_G_O(A)
Rainy Windy Soil	Composite HRS		-	ials	+	Cobalt (A,C)	_	Color ADMI (A)	X	Suspended Solids (A)		TTO (AE)
Fugitive Dust Other Seawater	X Grab	Other	-	ther	$\vdash$	Cooper (A,C)	_	Color Pt-Co (A)	_	TDS (A)		TTO Semi-Volatile (A)
LAB. SAMPLE # (LAB USE) DATE TIME	SAMPLE DESCRIPTION				-	Gold (A)		Conductivity (A)	_	TKN (A,B)		VOC's - TTO (A)
	OAMPLE DESCRIPTA		-		+-	Hardness (A,C)		Cyanide (A,D,G)	_	TOC (A,B)		MICROBIOLOGY
AT-18-238 05-24-18 0 940	Charca de	Sidmen	on	Sec	-	Iron (A,C)		D.O (A)	_	Turbidity (A)		Total Coliform (A,F)
	C. T. C. C.	-(01	1-10	1017	$\vdash$	Lead (A,C)	_	Fluoride (A)	_		$\vdash$	Fecal Coliform (A,F)
					-	Lithium (A,C)	_	lodide (A)	H	RCRA		HPC (A,F)
		-			-	Magnesium (A,C)	_	lodine (A) MLVSS (A)	_	Reactivity (A)		Enterococcus (A,F)
					-	Manganese (A,C)		Moisture (A)	H	Corrosivity (A)		E. Coli 0157 MPN (A,F)
					$\vdash$	Mercury (A,C)			$\vdash$	Ignitability (A)		Mold & Yeast (A,F)
					H	Molybdenum (A,C)	_	Nitrato & Nitrite (A) Nitrate (A)	Н	Metals - TCLP (A)		Salmonella (A,F)
					$\vdash$	Nickel (A.C)		Nitrite (A)	$\vdash$	Volatile - TCLP (A)	$\vdash$	Campylobacter(A,F)
						Polassium (A,C)		O&G Total (A,B)	┝	Semi-Volatile-TCLP (A)	ш	Listeria (A,F)
					1	Selenium (A,C)		O&G TPH (A,B)	$\vdash$	Pesticide - TCLP (A)	-	FOOD ANALYSES
					$\vdash$	Silicon (A,C)	_	Ortho Phosphate (A,B)	$\vdash$	Herbicide - TCLP (A) TOX (A)	$\vdash$	% Collagen
		, , , , , , , , , , , , , , , , , , ,			1	Silver (A.C)		Citilo Prospilate (A,b)	$\vdash$	TOX (A)	$\vdash$	% FAT
						Sodium (A,C)		O₂ mg/l	$\vdash$		$\vdash$	% Protein Water Activity - Aw
						Strontium (A,C)			_	/ ECEND DOS	950	VATION USED
						Thallium (A.C)		pH su	A	ice (Cool,4 °C)		HCL
						Tin (A.C)				H <sub>2</sub> SO <sub>4</sub>		Sodium Thiosfulfate
						Titanium (A,C)		Ternp °C		HNO <sub>1</sub>		Ascorbic Acid
					$\Box$	Vanadium (A,C)			_	Na OH	_	Zinc Acetate
						Zinc (A,C)		Cl <sub>2</sub> mg/l	Ť			Zino Apotato
Cliente solicitó que fue		· ·	Name and Address of the Owner, where	- A Control of the Co			TE	MPERATURE OF SAMPLE		The second secon		
Cliente solicità que fre	ic solanent	e T55.			CONDITIONS OF SAMPLES UPON RECEIPT				-	CONDITION SAMPLE	LABORATORYACTION	
					<u> </u>			Room Temperature		-Sample Intact	Z	-Sample Accepted
					The	mometer Serial #		Frozen		Properly Preserved		Sample Rejected
Sample Collected & Delice Late 44					LC	100	REC	EMED AT 2°C		Sample Compromised		
Sample Collected & Relinquished by (Finit name & sign):	Date: 5-36-12	Received by (F	rint name	(ngis 5 s		1		Date: 05-30-8	Del	ivery to Lab. by (Programe	å sigr	); \
" IVlavia Vida	1 The: 0930	Date	In	Cola	0	100			>	1 1		
Company O Malla 101								Time: 0930	4	Delwin (the	5	(2)
Company EC WESTE	Collector ID#	Collector ID# Company: ALCHEM CAB					Collector ID#	e:05-30-18	Time	e: /CAC		
Relinquished by (Print name & sign):	Date:	Pate: Received by (Print name & sign):			Date:		Date:	Received at Lab. by (Print name & sign):			1505	
	Time	Time:										1
2								Time:		Serve Cop.	nell	
Company:	Collector ID#	Collector ID# Company:				Hit commences to be a second of the second o		Collector ID#		9:	Time	e: , , , , ,
PROCEDURE NO: AL GAPOON			-						H	ay 30, 18		1505